

1. No
2. Yes
3. ~~Yes~~

To me the present keypad F/A/O is adequate. The other capabilities in question 3 are


desirable. My machine is crashing. Bally sent me a Service Manual + Hackers Manual but problem seems to be in one of the custom chips so back to factory for repair. The

Model No BA-1000-2  
Serial No 3237

Tutorials & programs  
comments are much  
appreciated.

Lipai Kugman

L. Kingman  
Rt 1 Box 71A  
Chester, Md 21619



Robert Fabris  
3626 Marie Drive  
San Jose, CA 95127